Vu-Graph Index



- Process Overview
- 2. Materials and Code Basics Handy Materials Reference
- 3. Desalters and Their Preheaters
- 4. Caustic Cracking and Corrosion
- 5. Hot H₂S Corrosion (Sulfidation)
- 6. Naphthenic Acid Corrosion
- Corrosion by HCI
- 8. Corrosion by Ammonium Chloride
- 9. Ammonia SCC
- 10. Corrosion by Amine Hydrochloride
- 11. Chloride Stress Corrosion Cracking
- 12. Crude Unit Overhead Corrosion Control
- 13. Embrittlement Mechanisms
- 14. Brittle Fracture
- 15. Creep
- 16. Wet H₂S Cracking
- 17. Polythionic Acid SCC
- 18. SCC Class Exercise
- 19. Graphitization
- 20. Spec Breaks
- 21. Corrosion at Injection Points
- 22. Summary Materials Degradation in Crude Units
- 23. Corrosion Under Insulation
- 24. Process Variables
- 25. Corrosion Monitoring Guidelines
- 26. Oxidation

Confidential
Copyright © 2011 by
Chevron Energy Technology Company
To be reproduced and used only in accordance with
written permission of ETC